



## Treating HVAC Tubing Coils with EnerFreeze™



15 year old untreated Suction Line

The image above depicts a segment of copper coil tubing from a 5 ton A/C Roof Top Unit in regular service for 15 years.

The images below were recorded 10 days after EnerFreeze was injected into the system. The images show the complete removal of "Oil Fouling" and the treated surfaces left clean, smooth and protected from further fouling.



EnerFreeze Treated Suction Line at Compressor

EnerFreeze Treated Compressor to Condenser Coil

EnerFreeze Treated Liquid line from Condenser Coil to Evaporator